

Club at Norwich Inn - Landscape Project

1988 Old Pond Lane, Norwich, CT 06360

Phase 1A and 1B Project Summary

	Phase 1A Work Su	ummary	
Item			
1.0	Cost to Address Drainage Issue Behind Bldg 10	Notes:	
			1. See individual spreadsheets for breakout of co
	<mark>Sub Total \$ 835.</mark>	<mark>33</mark>	2. Scope of work is detailed on each worksheet
ltem 2.0	Cost to Address Cidewall, Densire at Didas 10 and 11		
2.0	Cost to Address Sidewalk Repairs at Bldgs 10 and 11		
	Concrete Walk Repair - Sub Total \$ 7,124.	57	3. Price Includes optional walk repair at Bldg 10
		57	5. The meldes optional wark repair at blag 10
	Phase 1A - Total Cost \$ 7,959.9	0	
	Phase 1A - Extra Work \$ 2,285.6		
	Phase 1A - Revised Total Cost \$ 10,245.5	7	
	Phase 1B Work Su	<u>immary</u>	
Item			
3.0	Cost to Install Paver Pool Deck and Walk at Clubhouse #2	2	
	Sub Total \$ 10,883.	13	
ltem			
4.0	Cost to Address Sample Trash Walk at Bldg 5		
410	cost to hadress sumple thash than at blag s		
	Sub Total \$ 749.	51	
	Phase 1B - Total Cost \$ 11,632.6	<mark>54</mark>	
	Phase 1B - Extra Work <u>\$ 6,456.9</u>	<u>)7</u>	
	Phase 1A - Revised Total Cost \$ 18,089.6	51	
	Phase 1A and 1B - Invoice Summary		
	Phase 1A and 1B - Final Total Cost \$ 28,335.1		Prepared by Dane J. White, P.E.
	Deposit Received \$ (3,918.5	•	Perfect Curb, LLC - Owner/Gen Mgr
	Deposit Received \$ (5,877.7		CT License # - HIC.0636253
	Phase 1A Extra Work Payment Received \$ (2,285.6	<u>57)</u>	May 25, 2019
	Phase 1A and 1B - Balance Due \$ 16,253.2	24	